

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 6A




FIG. 7




FIG. 7A




FIG. 8

Appl Of: Enric AMOROS et al.; Filed
3/1/02; For: Piezoelectric Ignition
Mechanism; Atty Dkt # 618-1018; Tel:
202-496-4400; Sht 11 of 17





FIG. 9






FIG. 11




FIG. 12

Appl Of: Enric AMOROS et al.; Filed
3/1/02; For: Piezoelectric Ignition
Mechanism; Atty Dkt # 618-1018; Tel:
202-496-4400; Sht 15 of 17




FIG. 13




FIG. 14




FIG. 14A